## TO BE FILLED BY THE INSPECTING OFFICER

( Assistant Engineer / Assistant Executive Engineer ) ( Re:G.O Ms 20/70/PWD Dt 23-01-1970 )

1	Name of School/Institution :	The Green Hills	Public School, Moolankave
		Noolpuzha Gran	na Panchayath, Wayanad
2	Name of the Officer :		peed, Asst: Engineer
			n Noolpuzha Grama Panchayath
3	Location with name of Education :	S Bathery	
1	District / sub.disteict	wayanad	
4	Period from which the certificate is issued	2024.05	
	issueu :	2024-25	RCC BUILDING NO 1
5	Types of building :	GF	1x6.23mx9.63mx3.60 M Office Room
·	Types of ballang	Gi	1x6.23mx13.69mx3.60 M Class Room
			5x6.23mx6.23mx3.60 M Class Room
			1x6.23mx6.23mx3.60 M Visitors Room
			1x6.23mx6.10mx3.60 M Principal Room
			1x6.23mx6.10mx3.60 M Visitors Room
			1x3.00mx6.10mx3.60 M Staff Room
			1x8.00mx8.13mx3.60m Center hall
		FF	8x6.23mx6.10mx3.60 M Class Room
			1x6.23mx11.60mx3.60 M Class Room
			1x6.23mx9.63mx3.60 M Class Room
			1x8.00mx7.11mx3.60 M Conference Hall
			1x3.00mx6.10mx3.60 M Staff Room
		SF	8x6.23mx6.10mx3.60 M Class Room
			1x6.23mx6.10mx3.60 M Class Room
			1x6.23mx10.86mx3.60 M Class Room
			1x8.00mx13.44mx3.60m Class Room
			RCC BUILDING NO 2
		CF	3x6.28mx6.27X3.60m Classroom
		GF	1x3.10mx6.50X3.60m Store room
			1x15.90mx6.50X3.60m Lab rooms
			1x10.50mx6.50X3.60m Lab rooms
			1x11.95mx6.50X3.60m Lab rooms
			2x6.28mx6.50X3.60m Classroom
			3x6.00mx6.70X3.60m Classroom
		FF	7x6.20mx6.50X3.60m Classroom
			1x6.20mx6.50X3.60m Staff room 1x3.60mx6.50X3.60m Office room
		SF	7x6.20mx6.50X3.60m Classroom
		SF	1x6.20mx6.50X3.60m Staff room
			1x3.60mx6.50X3.60m Office room
			TERRACE FLOOR
			1x16.93mx6.50 Dormitory
			1x16.93mx1.80 Verandah
			1x3.80mx3.95x3.60m Office
6	Nature of defect any		Silver Silver
	a).Foundation and basement :	nil	
	b).Superstructure :	nil	
	c).Doors and Windows :	nil nil	
	d).Wood work wrought and put up : e).Roof :	nil	
	f).Flooring :	nil	
	g).Miscellaneous (Cracks if any ) :	nil	
7	Any major defect noticed which will		
	render the building unsafe in any		
0	manner :	nil	
8	Whether maintenance work have been done properly :	VOC	
9	Whether the structure is sound or not	yes	
	and an addition is south of flot		